

Machine receiving process.

SN. 7136

Indicate if machine has chip conveyor then tag the chip conveyor.

Chip conveyor included.

Indicate if the machine has a coolant pump and how many.

Coolant pump included.
2 high pressure pumps.

List all tooling.

None

List all work holders.

None

List all collets.

None

Give the number of pucks and mark if any are missing.

Total - 5
Missing - 1

Put all tooling, work holders and pucks in a box and mark. _____

List any Sheet metal damage.

None

Make sure all turret plugs are on machine.

Missing - 0

Check voltage of machine and put a pigtail on accordingly. ✓

Power machine on and state the condition.

Power supply needs replaced

Move all axis. Note any concerns.

X-axis ballstrew noisy

Run tool changer. Note any concerns.

Upper and lower turrets need seals replaced

Run spindles. Note any concerns.

Sub-spindle needs rebuilt

Run parts catcher and conveyor. Note any concerns.

Good

Check all axis backlash readings. Record.

Note any leaking concerns.

Hydraulic cap missing

Note any other concerns.

Rubber for wipers

Ejector sensor needs replaced

Window broken

Bed fan and Radiator fan need replaced

Relays and jump to IO Check

Panel for fans missing

Drake for x-axis upper turret

Luke Shaw
Signature

11/12/20
Date